

Pavements

Asphalt

Liquid

List # 3.05.45

Page 1 of 2

Date: 01-Dec-2020

CUSTODIAL OFFICE : MERO - Bituminous - (416) 235-3715

Company	Product Identity	Categoric Use Description	Supply Points
Husky Energy (Head Office) PO Box 6525, Sta "D" Calgary AB T2P 3G7 Fax: 403-298-6161 Email: asphalt.inquiries@huskyenergy.com Web: www.huskyasphalt.com	MTO Primer	Primer	Winnipeg & Lloydminster
	MC30	Medium Curing	Winnipeg & Lloydminster
	MC70	Medium Curing	Winnipeg & Lloydminster
	MC250	Medium Curing	Winnipeg & Lloydminster
	MC800	Medium Curing	Winnipeg & Lloydminster
	MC3000	Medium Curing	Winnipeg & Lloydminster
	SC70	Slow Curing	Winnipeg & Lloydminster
	SC250	Slow Curing	Winnipeg & Lloydminster
	SC800	Slow Curing	Winnipeg & Lloydminster
	SC3000	Slow Curing	Winnipeg & Lloydminster
McAsphalt Industries Ltd. 8800 Sheppard Avenue East Toronto ON M1B 5R4 Tel: 416-281-8181 Fax: 416-281-8842 Toll Free: 800-268-4238 Email: info@mcasphalt.com Web: www.mcasphalt.com	MTO Primer	Primer	Oshawa
	MTO Primer	Primer	Ottawa
	RC30	Rapid Curing	Oshawa
	RC30	Rapid Curing	Ottawa
	RC30	Rapid Curing	Thunder Bay
	RC30	Rapid Curing	North Bay
	RC70	Rapid Curing	Oshawa
	RC70	Rapid Curing	Thunder Bay
	RC70	Rapid Curing	North Bay
	RC250	Rapid Curing	Oshawa
	RC800	Rapid Curing	Oshawa
	RC3000	Rapid Curing	Oshawa
	RC3000	Rapid Curing	Ottawa
	MC30	Medium Curing	Oshawa
	MC70	Medium Curing	Oshawa

Pavements**Asphalt****Liquid****List # 3.05.45**

Page 2 of 2

Date: 01-Dec-2020

CUSTODIAL OFFICE : MERO - Bituminous - (416) 235-3715

Company	Product Identity	Categoric Use Description	Supply Points
McAsphalt Industries Ltd. 8800 Sheppard Avenue East Toronto ON M1B 5R4 Tel: 416-281-8181 Fax: 416-281-8842 Toll Free: 800-268-4238 Email: info@mcasphalt.com Web: www.mcasphalt.com	MC250	Medium Curing	Oshawa
	MC250	Medium Curing	Thunder Bay
	MC800	Medium Curing	Oshawa
	MC3000	Medium Curing	Oshawa
	MC3000	Medium Curing	Ottawa
	MC3000 Special	TBI	Oshawa
	SC70	Slow Curing	Oshawa
	SC70	Slow Curing	Ottawa
	SC250	Slow Curing	Oshawa
	SC800	Slow Curing	Oshawa
	SC800	Slow Curing	Thunder Bay
	SC800	Slow Curing	North Bay
	SC3000	Slow Curing	Oshawa
	MIP	TBI	Oshawa